
Illustration of surface mounted accessory



- 1. Remove the terminal block cover
- 2. Install the ceiling bracket and then connect the supply conductors to the terminal and replace the terminal block cover
- 3. Rotate the ceiling house clockwise and fix it to the ceiling bracket.
- 4. Lock the safety lanyard and connect the earth conductor and DC output conductors, test and energize